







## List of Modifications and/or Service Bulletins (Doc. P2008/1049) Applied on P2008-JC S/n 1049




n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	VISTO C.Q.
MOD 2008/005	1	0	Garmin G3X software version 8.40 installation	m	Tecnam Approval DOA n° Mod.2008/005	
MOD 2008/006	1	0	Central tunnel ABS cover	m	Tecnam Approval DOA n° Mod.2008/006	
MOD 2008/007	1	0	Stabilator additional drain holes	m	Tecnam Approval DOA n° Mod.2008/007	
MOD 2008/008	1	0	GNC255 Software Upgrade 2.02	m	Tecnam Approval DOA n° Mod.2008/008	
MOD 2008/011	1	0	New door lock system installation	m	Tecnam Approval DOA n° Mod.2008/011	
MOD 2008/012	1	0	UMA T16-311-161 airspeed ind. Installation	m	Tecnam Approval DOA n° Mod.2008/012	
MOD 2008/013	1	0	Engine Instrument adapters	m	Tecnam Approval DOA n° Mod.2008/013	
MOD 2008/016	1	0	Nose landing gear fairing design improvement	m	Tecnam Approval DOA n° Mod.2008/016	
MOD 2008/018	1	0	Brake pump attachment relocation	m	Tecnam Approval DOA n° Mod.2008/018	
MOD 2008/019	1	0	Throttle system improvement	m	Tecnam Approval DOA n° Mod.2008/019	
MOD 2008/021	1	0	Led strobe/NAV/POS light electrical system improvement	m	Tecnam Approval DOA n° Mod.2008/021	
MOD 2008/022	1	0	Gascolator fitting change	m	Tecnam Approval DOA n° Mod.2008/022	
MOD 2008/023	1	0	Seat track improvement	m	Tecnam Approval DOA n° Mod.2008/023	
MOD 2008/025	1	0	NLG Wheel Hub Improvement	m	Tecnam Approval DOA n° Mod.2008/0225	

## List of Modifications and/or Service Bulletins (Doc. P2008/1049) Applied on P2008-JC S/n 1049

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	VISTO C.Q.
MOD 2008/026	1	0	Stabilator pin change	m	Tecnam Approval DOA n° Mod.2008/026	
MOD 2008/028	1	0	Fuselage fatigue life extension	M	EASA N° 10051279	
MOD 2008/029	1	0	Hoffman propeller for P2008JC	M	EASA N° 10052448	
MOD 2008/030	1	0	Alternate intake air design improvement	m	Tecnam Approval DOA n° Mod.2008/030	
MOD 2008/033	1	0	Baggage compartment floor improvement	m	Tecnam Approval DOA n° Mod.2008/033	
MOD 2008/041	1	0	Change of measurement method from CHT to CT for ROTAX Engine Type 912	M	EASA N° 10035858	
MOD 2008/043	1	0	Flap actuator cap improvement	m	Tecnam Approval DOA n° Mod.2008/043	
MOD 2008/046	1	0	Door locking system improvement	m	Tecnam Approval DOA n° Mod.2008/046	
MOD 2008/050	1	0	ELT KANNAD	m	Tecnam Approval DOA n° Mod.2008/050	
MOD 2008/055	1	0	Carb heat control system improvement	m	Tecnam Approval DOA n° Mod.2008/055	
MOD 2008/056	1	0	GTR225A Installation	m	Tecnam Approval DOA n° Mod.2008/056	

Tecnam S.B. n° 134-CS	1	0	ACF-50 Use on all Tecnam Aircrafts	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	
Tecnam S.B. n° 142-CS	1	0	P2008 JC incorrect VOR indication due to Garmin GNC 255 software bug	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	
Tecnam S.B. n° 147-CS	1	0	Exhaust Springs Set-Up	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	
Tecnam S.B. n° 152-CS	1	0	Exhaust Springs Safety Wire Installation	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	

**List of Modifications and/or Service Bulletins (Doc. P2008/1049)  
Applied on P2008-JC S/n 1049**

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	VISTO C.Q.
Tecnam S.B. n° 165-CS	1	0	Exhaust System Anti-Size Copper grease Application	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	
Tecnam S.B. n° 167-CS	1	0	P2008 JC Fuselage fatigue life extension	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	
Tecnam S.B. n° 168-CS	1	0	Hoffmann propeller installation on P2008 JC	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	

Data 15-07-2015 Visto Certifying Staff Antonio Oliviero 